

DUREMAX® GPE

General Purpose Epoxy Coating

PC 255

FEATURES

- EXCELLENT RESISTANCE TO HOT WATER IMMERSION (80°C)
- COMPATIBLE OVER MOST TYPES OF PROPERLY APPLIED & TIGHTLY ADHERING COATINGS
- EASE OF APPLICATION SPRAY, BRUSH, ROLLER
- CHOICE OF HARDENERS FOR VARYING CLIMATIC CONDITIONS
- POTABLE WATER APPROVAL
- GOOD ABRASION RESISTANCE
- WIDE RANGE OF COLOURS AVAILABLE FROM THE COLORFAST TINT SYSTEM
- AVAILABLE IN MICACEOUS IRON OXIDE FINISH

USES

DUREMAX® GPE has been locally developed specially for Australasian conditions using the latest epoxy technology. It is a general-purpose epoxy coating used on steel, galvanising and concrete. DUREMAX® GPE is a high performance coating for the protection of structures exposed to severe environments such as chemical plants, offshore platforms, refineries, shiploaders, coal wash plants etc. Untinted DUREMAX® GPE is suitable for fresh and salt-water immersion except when cured with Quickturn™ hardener. It is compatible over inorganic zinc and epoxy primers and can be topcoated with a wide range of coating types.

SPECIFICATIONS

AS4020 for use with potable water when using White with Fast Cure only.

RESISTANCE GUIDE

HEAT RESISTANCE	Up to 120°C dry heat.	ALKALIS	Suitable for splash and spillage of strong alkali.
WEATHERABILITY	Epoxy coatings may yellow with time. On exterior exposure some chalking may also occur. This will not detract from the protective properties of the	SALTS	Excellent resistance to neutral and alkali salts.
	coating. Use a weatherable topcoat if required for appearance.	WATER	Excellent resistance to immersion in fresh and salt water. Tinted colours and aluminium containing colours are not
SOLVENTS	Resists splash and spillage of most hydrocarbon solvents, refined petroleum products and most common alcohols.	ABRASION	recommended for immersion conditions. Good when fully cured.
ACIDS	White and colours are suitable for splash and spillage of mild acids.		

TYPICAL PROPERTIES AND APPLICATION DATA

		I LIGATION DATA					
CLASSIFICATION FINISH COLOUR	Semi Gloss (E White, Black,	Light Grey, MIO Mid nge of tinted colours and	APPLICATION CONDITIONS Refer to Page 2				
COMPONENTS SOLIDS BY VOLUME VOC LEVEL FLASH POINT POT LIFE (4L, 25°C) MIXING RATIO (V/V)	Two Refer to Page Refer to Page 4°C Refer to Page Part A: 4	2	Wet film per coat (microns) Dry film per coat (microns)	Min Max Recom. Refer to Page 2			
THINNER	920-08925 920-81942	Dulux® Epoxy Thinner DUTHIN® 450 *	SUITABLE SUBSTRATES	Blast cleaned steel. Prepared concrete, aluminium and galvanised steel.			
PRODUCT CODE	780-63001 780-63002 780-63003	White/Light Base Deep Base Clear Base	APPLICATION METHODS	Brush, roller, conventional or airless spray.			

DUTHIN® 450 is the preferred thinner for application in cold conditions.

780-63006

780-38678

780-50585

976-84577

976-84741

976-84892

MIO Mid Grey

Standard Hardener

Fast Cure Hardener

Quickturn™ Hardener

Light Grey

Black

DUREMAX	® GPE								
Standard Ha	rdener								
COATING THICKN Wet film per coat (m	nicrons)	Min 140 100	Max 280 200	Recom. 175 125	APPLICA ⁻	Relative Humid	e ace Temperature ity	Min 10°C 10°C	Ma 45° 45° 85
SOLIDS BY VOLUI VOC LEVEL		nite) (White, un	tinted)		POT LIFE	Concrete Moist	ure Content 3-4 Hours (4L, 25	5°C)	<10
Drying characteris	stics at 125 micro	ons dry fil	m thickn	ess			0		
Temperature	Humidity	To	uch	Har	ndle	Full Cure	Min	ercoat M	ах
10° C	50%		Hours		lours	7 Days	28 Hours	4 We	
15° C	50%	12 1	Hours		lours	7 Days	20 Hours	4 We	
25° C	50%	4 H	lours	10 H	lours	7 Days	8 Hours	4 We	eks*
Fast Cure Ha	ardener				method an	d conditions of a	pplication and surface	ce roughnes	SS.
COATING THICKN	FSS				APPLICAT	TION CONDITIO	NS		
		Min	Max	Recom.	7			Min	N
Wet film per coat (m	nicrons)	135	270	170		Air Temperatur	е	5°C	45
Dry film per coat (m	icrons)	100	200	125		Substrate Surfa	ace Temperature	5°C	45
						Relative Humid Concrete Moist	-7		8! <10
						Concrete Moist	ure Content		-10
SOLIDS BY VOLUI VOC LEVEL		iite) (White, un	tinted)		POT LIFE		2 Hours (4L, 25°0	C)	
Drying characteris				ess					
Tomporoturo	Humidity	т.	uch	Цая	ndle	Full Cure	Ov Min	ercoat M	
Temperature 5° C	50%		lours		lours	7 Days	18 Hours	4 We	
10° C	50%		lours		lours	7 Days 7 Days	14 Hours	4 We	
15° C	50%		lours		lours	7 Days	10 Hours	4 We	
25° C	50%		Hours		ours	7 Days	6 Hours	4 We	
TYPICAL SPREAD DRY FILM BUILD	ING RATE AT R	ECOMME	NDED		microns dr Practical s	y film thickness a preading rates w	metres per litre corrassuming no losses. ill vary depending or pplication and surfac	n such facto	ors as
Quickturn [™] I	Hardener								
COATING THICKN	FSS				APPLICA:	TION CONDITIO	NS.		
COATING THICKIN		Min	Max	Recom	AI I LICA			Min	M

Quickturn [™] Hard	lener						
COATING THICKNESS				APPLICAT	ION CONDITIONS		
Wet film per coat (microns Dry film per coat (microns	,	Max 280 200	Recom. 175 125		Air Temperature Substrate Surface Temperature Relative Humidity Concrete Moisture Content	Min 5°C 5°C	Max 35°C 35°C 85% <10%
SOLIDS BY VOLUME VOC LEVEL	72% (White) <310 g/L (White, unti	nted)		POT LIFE	90 Minutes (4L,	25°C)	

Drying characteristics at 125 microns dry film thickness

					Overcoat		
Temperature	Humidity	Touch	Handle	Full Cure	Min	Max	
5° C	50%	7 Hours	14 Hours	7 Days	14 Hours	4 Weeks*	
10° C	50%	5 Hours	9 Hours	7 Days	9 Hours	4 Weeks*	
15° C	50%	3 Hours	5 Hours	7 Days	5 Hours	4 Weeks*	
25° C	50%	90 Minutes	3 Hours	7 Days	3 Hours	4 Weeks*	

TYPICAL SPREADING RATE AT RECOMMENDED	A spreading rate of 5.8 sq. metres per litre corresponds to 125
DRY FILM BUILD	microns dry film thickness assuming no losses.
	Practical spreading rates will vary depending on such factors as
	method and conditions of application and surface roughness.

These figures are given as a guide only, as ventilation, film thickness, humidity, thinning and other factors will influence the rate of drying. If the maximum overcoat interval is exceeded then the surface MUST be abraded to ensure maximum intercoat adhesion.

Use of fast or low temperature hardeners may result in increased yellowing and a reduction of gloss level.

July 2013 Page 2 of 4 PC 255

^{*} When used for non-immersion conditions. Refer to PRECAUTIONS section for overcoating intervals and requirements for immersion service.

DUREMAX® GPE TYPICAL SYSTEMS

(The typical systems are offered as a guide only and are not to be used as a specification. It is recommended that the specific needs of a project be discussed with a Dulux Protective Coatings Consultant.)

SURFACE	PREPARATION GUIDE		SYSTEM	DRY FILM THICKNESS
STEEL New Construction	Abrasive blast AS1627.4 Class 2.5	1st Coat 2nd Coat 3rd Coat	ZINCANODE® 402 DUREMAX® GPE WEATHERMAX® HBR	75 Microns 125 Microns 100 Microns
		1st Coat 2nd Coat	DUREMAX [®] GPE ZP DUREMAX [®] GPE	125 Microns 125 Microns
		1st Coat	DUREMAX® GPE	125 - 200 Microns
STEEL Immersion -Salt or Freshwater	Abrasive blast to AS1627.4 Class 3.0	1st Coat 2nd Coat	DUREMAX® GPE DUREMAX® GPE (untinted colour only)	125 Microns 125 Microns
CONCRETE	Clean surface to remove contaminants. Diamond grind, track or light-shot blast. Remove dust.	1st Coat 2nd Coat	DUREMAX® GPE DUREMAX® GPE (Thin first coat 10-15%)	125 Microns 125 Microns
GALVANISED, ALUMINIUM	Clean, degrease and abrade surface by whip blasting.	1st Coat 2nd Coat	DUREMAX® GPE WEATHERMAX® HBR	150 Microns 100 Microns

SURFACE PREPARATION

Steel: Round off all rough welds, sharp edges and remove weld spatter. Remove grease, oil and other contaminants in accordance with AS1627.1. For steel substrates, abrasive blast clean to a minimum of AS1627.4 Class 2.5 with a blast profile of 40-70 microns. For non-ferrous substrates whip blast. Immersed steel must be prepared to AS1627.4 Class 3. Remove all dust by brushing or vacuum cleaning. Concrete: Remove all laitance, form release, curing compounds, oil, grease and other surface contaminants. Diamond grind, track or light shot-blast to provide suitable profile. Remove all dust by vacuum cleaning. Fill any large voids exposed using Luxepoxy Filler. Cement based substrates should be at least 21 days old before coating.

APPLICATION

Stir each can thoroughly until the contents are uniform. Use of a power mixer is recommended. Ensure bases have been tinted to the correct colour before use – DULUX ASSUMES NO RESPONSIBILITY FOR THE APPLICATION OF AN INCORRECT COLOUR. Mix the contents of both packs together thoroughly using a power mixer and allow to stand for 10 minutes. Box all containers before use to ensure colour consistency. Remix thoroughly before using.

BRUSH/ROLLER

Apply even coats of the mixed material to the prepared surface. When brushing and rolling additional coats may be required to attain the specified thickness.

CONVENTIONAL SPRAY

Thinning is not normally required, however a small amount (5% or less by volume) of Dulux® Epoxy

Thinner (920-08925) or DUTHIN® 450 * (920-81942).

Typical Set-up

Oracle Date Outside (920-842)

 Graco Delta Gun:
 1.8mm (239543)

 Pressure at Pot:
 65-100 kPa (10-15 p.s.i.)

 Pressure at Gun:
 380-415 kPa (55-60 p.s.i.)

AIRLESS SPRAY

Standard airless spray equipment such as a Graco 45:1 Xtreme with a fluid tip of 17-21 thou (0.43-0.53mm) and an air supply capable of delivering 550-690 kPa (80 -100 psi) at the pump. Thinning is not normally required but up to 50ml/litre of Dulux® Epoxy Thinner (920-08925) or DUTHIN® 450 * (920-81942) may be added to ease application.

PRECAUTIONS

This is an industrial product designed for use by experienced Protective Coating applicators. Where conditions may require variation from the recommendations on this Product Data Sheet contact your nearest Dulux® representative for advice prior to painting. Do not apply in conditions outside the parameters stated in this document without the express written consent of Dulux® Australia. Freshly mixed material must not be added to material that has been mixed for some time. Do not apply at temperatures below 10°C when using Standard hardener or 5°C when using Fast Cure or Quickturn™ hardener. In cold conditions where a fast thinner is required DUTHIN® 450 * (920-81942). Do not apply at relative humidity above 85% or when the surface is less than 3°C above the dewpoint. Do not use Quickturn™ hardener for immersion conditions. When used for immersion conditions the maximum overcoat interval is 3 days. The coating MUST be fully cured and solvent free prior to being placed under immersion conditions. For best results in water immersion conditions replace Dulux® Epoxy Thinner (920-08925) with Dulux® CR Reducer (965-63020). Do NOT use as a primer over galvanised steel when using Fast Cure hardener as delamination can occur. Use of fast or low temperature hardeners may result in increased yellowing and a reduction of gloss level.

CLEAN UP

Clean all equipment with Dulux[®] Epoxy Thinner (920-08925) or DUTHIN[®] 450 (920-81942) immediately after use.

OVERCOATING

Aged coating should be tested for lifting by a method appropriate for the coating thickness, for example 'X' cut or cross-hatch methods. If it lifts, remove it. The surface must be free of oil, grease and other contaminants. High-pressure water wash at 8.3 to 10.3 MPa (1,200 - 1,500 p.s.i.) to remove loosely adhering chalk and dust. Abrasion may be required depending on surface condition. If the maximum overcoat interval is exceeded then the surface MUST be abraded to ensure maximum intercoat adhesion.

DUREMAX® GPE

SAFETY PRECAUTIONS Read Data Sheet, Safety Data Sheet and any precautionary labels on containers.

STORAGE Store as required for a flammable liquid Class 3 in a bunded area under cover. Store in well-ventilated

area away from sources of heat or ignition. Keep containers closed at all times.

HANDLING As with any chemical, ingestion, inhalation and prolonged or repeated skin contact should be avoided by

good occupational work practice. Eye protection approved to AS1337 should be worn where there is a risk of splashes entering the eyes. Always wash hands before smoking, eating, drinking or using the

toilet.

USING Use with good ventilation and avoid inhalation of spray mists and fumes. If risk of inhalation of spray

mists exists, wear combined organic vapour/particulate respirator. When spray painting, users should

comply with the provisions of the respective State Spray Painting Regulations.

FLAMMABILITY This product is flammable. All sources of ignition must be eliminated in, or near the working area. DO

NOT SMOKE. Fight fire with foam, CO₂ or dry chemical powder. On burning will emit toxic fumes.

SAFETY DATA SHEET is available from Dulux Customer Service (Australia 132 377 or New Zealand 0800 800 424) www.duluxprotectivecoatings.com.au

Dulux Protective Coatings a division of

DuluxGroup (Australia) Pty Ltd 1956 Dandenong Road, Clayton 3168 A.B.N. 67 000 049 427 DuluxGroup (New Zealand) Pty Ltd 150 Hutt Park Road, Lower Hutt, NZ A.B.N. 55 133 404 118

Dulux, Zincanode, Duremax, Weathermax and Duthin are registered trade marks and Quickturn and Colorfast are trade marks of DuluxGroup (Australia) Pty Ltd.

PACKAGING TRANSPORTATION WEIGHT

TRANSPORTATION WEIG DANGEROUS GOODS Available in 4 litre and 15 litre packs 1.6 kg/litre (Average of components) Part A: Class 3 UN 1263

Part B: Class 8,3 UN 2734 (Standard)

Any advice, recommendation, information, assistance or service provided by DULUX Australia in relation to goods manufactured by it or their use and application is given in good faith and is believed by Dulux to be appropriate and reliable. However, any advice, recommendation, information, assistance or service provided by Dulux is provided without liability or responsibility PROVIDED THAT the foregoing shall not exclude, limit, restrict or modify the right entitlements and remedies conferred upon any person or the liabilities imposed upon Dulux by any condition or warranty implied by Commonwealth, State or Territory Act or ordinance void or prohibiting such exclusion limitation or modification. Products can be expected to perform as indicated in this sheet so long as applications and application procedures are as recommended. Specific advice should be sought from Dulux for application in coastal areas and for large projects to ensure proper performance.